

No.	Picture	Replaces following OEM's	Competitor Xref Part #'s	Used on	Suggested Retail Price
1	 <p><b>TY1017</b></p>	<p><b>AC DELCO:</b> F523  <b>FORD:</b> 1L2U12029AA, 1L2U12A366AA, 1L2Z12029AA, 1L5Z12029AA, 3W7Z12029AA, F7TZ12A336BA, F7TZ12029AB, F7TZ12029BA, F7TZ12029CC, F7TU12A336AB, F7TU12A336BA  <b>GM:</b> 88921369  <b>MOTORCRAFT:</b> DG467, DG472, DG473, DG479, DG481, DG491, DG508</p>	<p><b>KEM:</b> 346S  <b>NAPA/Eichlin:</b> IC369, IC369SB  <b>Standard:</b> FD503  <b>Wells:</b> C1139, C1417</p>	<p><b>Ford:</b> '97-'06  <b>Lincoln:</b> '98-'02  <b>Mercury:</b> '98-'02</p>	\$24.37
2	 <p><b>TY1018</b></p>	<p><b>AC DELCO:</b> F524  <b>FORD:</b> 1F3U12029AA, 1F3Z12029AA, 1F3Z12029AC, 2C6Z12029AA, D7LZ12029AA, F7LU12A366AD, F7LU12A366CB, F7LU12029AC, F7LU12029CC, F7LZ12029AA, F7LZ12029AC, F7LZ12029AD, F7LZ12029CB  <b>GM:</b> 88921370  <b>MOTORCRAFT:</b> DG466, DG468, DG475, DG478, DG487, DG492</p>	<p><b>KEM:</b> 346T  <b>NAPA/Eichlin:</b> IC63, IC63SB  <b>Standard:</b> UF191  <b>Wells:</b> C1141</p>	<p><b>Audi:</b> '02-'03  <b>Ford:</b> '99-'03  <b>Lincoln:</b> '97-'03</p>	\$24.37
3	 <p><b>TY1021</b></p>	<p><b>AC DELCO:</b> F1953, F503  <b>FORD:</b> E2FZ12029A, E3FZ12029A, E73Z12029A, F3Z212029A, F3FU12029AA, F5FZ12029A, F5ZZ12029A, F7PZ12029AA  <b>GM:</b> 19017194  <b>MAZDA:</b> ZZM118100, ZZM418100, FS151810X  <b>MOTORCRAFT:</b> DG325, DG325A, DG434, DG462, DG463, DG470, DGE453</p>	<p><b>KEM:</b> 346F  <b>NAPA/Eichlin:</b> IC24, IC24SB  <b>Standard:</b> FD478X  <b>Wells:</b> C839</p>	<p><b>Ford:</b> '80-'97  <b>Lincoln:</b> '84-'94  <b>Mazda:</b> '94-'97  <b>Mercury:</b> '82-'95  <b>Merkur:</b> '85-'88</p>	\$22.78
4	 <p><b>TY1022</b></p>	<p><b>AC DELCO:</b> D503A, D535, D535B, D535CS, D537, D544, D560, D573  <b>AMC:</b> 8983501871  <b>GM:</b> 1047794, 1106013, 1115315, 1115317, 1115466, 1115468, 1115491, 10477208, 10477944, 12498334  <b>ISUZU:</b> 8011153150, 8011154660, 8011154680  <b>JEEP:</b> 83501871</p>	<p><b>KEM:</b> 342G  <b>NAPA/Eichlin:</b> IC29, IC29SB  <b>Standard:</b> DR37X  <b>Wells:</b> C846</p>	<p><b>Buick:</b> '85-'95  <b>Cadillac:</b> '85-'95  <b>Chevrolet:</b> '75-'95  <b>Geo:</b> '90-'93  <b>Oldsmobile:</b> '85-'86  <b>Pontiac:</b> '85-'95</p>	\$22.78
5	 <p><b>TY1023</b></p>	<p><b>AC DELCO:</b> D504A, D523, D530, D532,  <b>AMC:</b> J8131936  <b>CHRYSLER:</b> 8131936  <b>FORD:</b> C0NP12029A  <b>GM:</b> 1875894, 1985473, 1988665, 10497132,  <b>HARVESTER:</b> 1694925C1  <b>MOTORCRAFT:</b> DGG419</p>	<p><b>KEM:</b> 342E  <b>NAPA/Eichlin:</b> IC19, IC19SB  <b>Standard:</b> DR31X  <b>Wells:</b> C834</p>	<p><b>AMC:</b> '80-'81  <b>Buick:</b> '77-'87  <b>Cadillac:</b> '74-'90  <b>Checker:</b> '75-'77  <b>Chevrolet:</b> '74-'90  <b>GMC:</b> '75-'90  <b>Jeep:</b> '80-'81  <b>Oldsmobile:</b> '74-'87  <b>Pontiac:</b> '77-'87</p>	\$19.93

No.	Picture	Replaces following OEM's	Competitor Xref Part #'s	Used on	Suggested Retail Price
6	 <p><b>TY1026</b></p>	<p><b>AC DELCO:</b> D501A, D525, D526, D527, D528, D529, D529B, D529CS  <b>ALLIS CHALMERS:</b> 1187847  <b>CHRYSLER:</b> 8134003  <b>GM:</b> 1115444, 1115445, 1115447, 1115448, 1115455  <b>JEEP:</b> J8134003  <b>MOTORCRAFT:</b> DGG222, DGG322, DGG421</p>	<p><b>KEM:</b> 342D  <b>NAPA/Eichlin:</b> IC22, IC22SB  <b>Standard:</b> DR35  <b>Wells:</b> C835</p>	<p><b>AMC:</b> '82-'83  <b>Buick:</b> '75-'84  <b>Cadillac:</b> '82-'84  <b>Checker:</b> '75-'77  <b>Chevrolet:</b> '75-'84  <b>GMC:</b> '75-'84  <b>Jeep:</b> '82-'84  <b>Oldsmobile:</b> '75-'84  <b>Pontiac:</b> '75-'84</p>	\$22.78
7	 <p><b>TY2007</b></p>	<p><b>AC DELCO:</b> D539, D540, D555, D576  <b>GM:</b> 1103608, 1103646, 1103662, 1103663, 1103744, 1103745, 1103746, 10467067, 10468391, 10472401, 10477602, 10495121, 10497771  <b>ISUZU:</b> 106483910, 8011038300, 8106483910, 8104724010</p>	<p><b>KEM:</b> 342J  <b>NAPA/Eichlin:</b> IC39, IC39SB  <b>Standard:</b> DR39X  <b>Wells:</b> C849</p>	<p><b>Buick:</b> '86-'07  <b>Cadillac:</b> '87-'99  <b>Chevrolet:</b> '87-'05  <b>GMC:</b> '94-'03  <b>Honda:</b> '94-'95  <b>Isuzu:</b> '91-'97  <b>Oldsmobile:</b> '86-'04  <b>Pontiac:</b> '87-'07</p>	\$23.51
8	 <p><b>TY4001</b></p>	<p><b>AC DELCO:</b> E532D, E586A  <b>DAEWOO:</b> 96350585  <b>GM:</b> 88921374  <b>ISUZU:</b> 1104038, 8011040381</p>	<p><b>KEM:</b> 351H  <b>NAPA/Eichlin:</b> IC485  <b>Standard:</b> UF356  <b>Wells:</b> C1149</p>	<p><b>Daewoo:</b> '99-'02  <b>Isuzu:</b> '98-'03</p>	\$128.38
9	 <p><b>TY6001</b></p>	<p><b>AC DELCO:</b> D538, D543, D552  <b>GM:</b> 12353801, 24502008, 24502371, 22518356, 25523221, 25526448, 25533542</p>	<p><b>KEM:</b> 342H  <b>NAPA/Eichlin:</b> IC28, IC28SB  <b>Standard:</b> DR36  <b>Wells:</b> C860</p>	<p><b>Buick:</b> '86-'92  <b>Oldsmobile:</b> '86-'92  <b>Pontiac:</b> '86-'92</p>	\$52.15
10	 <p><b>TY6003</b></p>	<p><b>AC DELCO:</b> F509, F518  <b>DENSO:</b> 297006760, 297007180, 0297007910  <b>FORD:</b> 919F12029AA, E9SF12029AA, F5SU12029AA, F5SZ12029A, E9SZ12029A, F1SZ12029A  <b>GM:</b> 19017114  <b>JAGUAR:</b> LNA1508AA  <b>MOTORCRAFT:</b> DG440, DGE456, DG451</p>	<p><b>KEM:</b> 343G  <b>NAPA/Eichlin:</b> IC38, IC38SB  <b>Standard:</b> FD488  <b>Wells:</b> C901</p>	<p><b>Ford:</b> '89-'01  <b>Mercury:</b> '89-'01</p>	\$73.64